




Site Report To attend site as per client's instructions to carry out cleaning of kitchen soil vent pipes.







picote machine showing
sludge on cable



flat cleaned after and
tested