



CCTV drainage survey report

SITE INFORMATION

Client:

Site Address

Survey No:

Survey date:

Report completed by: Chris Reeve (OS20X) WRc qualified

Date of issue:

INTRODUCTION

CLIENT INFORMATION

Client

Client Reference:

Contact Name:

Client Address:

Survey No:

Date(s) of site works:

Operatives on site:

Report completed by:



Scope of works: CCTV drainage survey

REPORT CONTENTS	
1.	Covering letter
2.	CCTV survey report using Wincan software to MSCC5 standard
3.	Structural manhole chamber details
4.	Drainage plans
5.	Site photos
6.	Summary Recommendations if remedial repairs are required
7.	Standard defect codes, clock references used, deformation percentages, water/debris levels

DRAINAGE REPORT

SURVEY No:

Site Address:

SUMMARY OF FINDINGS

Instructions received by the client to complete a below ground drainage CCTV survey.

- Attended site to complete a below ground CCTV drainage survey.
- Client requires a drainage survey as part of Landlord's planning permission.
- Survey identified structural defects were observed to the below ground drainage.
- Drainage repairs are required as identified below.



SURVEY No: **Site Address:**

SUMMARY REPAIR RECOMMENDATIONS

INSPECTION	FROM (NODE) TO (NODE)	DEFECT DETAILS	RECOMMENDATION	PRIORITY
SECTION 1	MHCW02 – MHCW01	Drain has previously been repaired using epoxy patch lining methods. Where the patch liners end, further structural defects observed. Structural defects observed to include cracked pipe work. Insitu repairs using CIPP lining methods required. QUOTATION TO FOLLOW BY SEPARATE COVER		REPAIRS REQUIRED
SECTION 2	RAINWATER PIPE – MHCW01	No structural defects observed		NO REPAIRS REQUIRED
SECTION 3	BASEMENT TOILET – MHCW01	No structural defects observed		NO REPAIRS REQUIRED
SECTION 4	MHCW01 – PUBLIC SEWER	Drain has previously been repaired using CIPP lining methods. Where the liners end, further structural defects observed. Structural defects observed to include cracked and fractured pipe work. Insitu repairs using CIPP lining methods required. QUOTATION TO FOLLOW BY SEPARATE COVER		REPAIRS REQUIRED
SECTION 5	GULLY – MHCW02	No structural defects observed		NO REPAIRS REQUIRED
SECTION 6	ACO CHANNEL DRAIN – MHCW02	No structural defects observed		NO REPAIRS REQUIRED

Unit 42, Greenway Business Centre Harlow Business Park Harlow CM19 5QE Tel: 01279 456008
admin@knightanddayltd.co.uk Company Number: 11639814





SURVEY No: **Site Address:**

Site photos

FRONT OF THE PROPERTY



Unit 42, Greenway Business Centre Harlow Business Park Harlow CM19 5QE Tel: 01279 456008
admin@knightanddayltd.co.uk Company Number: 11639814





SURVEY No:

Site Address:

Site photos

FRONT OF THE PROPERTY



Unit 42, Greenway Business Centre Harlow Business Park Harlow CM19 5QE Tel: 01279 456008
admin@knightanddayltd.co.uk Company Number: 11639814





SURVEY No:

Site Address:

Site photos

MANHOLE MHCW01 AT THE FRONT OF THE PROPERTY (BLOCKED UPON ARRIVAL)



Unit 42, Greenway Business Centre Harlow Business Park Harlow CM19 5QE Tel: 01279 456008
admin@knightanddayltd.co.uk Company Number: 11639814






SURVEY No: Site Address:

Site photos

MANHOLE MHCW01 AT THE FRONT OF THE PROPERTY



Unit 42, Greenway Business Centre Harlow Business Park Harlow CM19 5QE Tel: 01279 456008
admin@knightanddayltd.co.uk Company Number: 11639814





SURVEY No:

Site Address:

Site photos

MANHOLE MHCW01 AT THE FRONT OF THE PROPERTY



Unit 42, Greenway Business Centre Harlow Business Park Harlow CM19 5QE Tel: 01279 456008
admin@knightanddayltd.co.uk Company Number: 11639814







SURVEY No: Site Address:

Site photos

MANHOLE MHCW02 AT THE REAR OF THE PROPERTY



Unit 42, Greenway Business Centre Harlow Business Park Harlow CM19 5QE Tel: 01279 456008
admin@knightanddayltd.co.uk Company Number: 11639814





SURVEY No: Site Address:

Site photos

MANHOLE MHCW02 AT THE REAR OF THE PROPERTY



Unit 42, Greenway Business Centre Harlow Business Park Harlow CM19 5QE Tel: 01279 456008
admin@knightanddayltd.co.uk Company Number: 11639814

